


Stand } ~~11-02-07~~
Issue } 11-05-04

Stand } 11-02-07
Issue } 11-05-04


Fig./Abb. 1

This exploded view diagram illustrates the assembly of a Bosch power tool. The central component is the main body (1), which features the Bosch logo and a control knob (2). Surrounding the main body are various accessories and components, each labeled with a number: 3 (a small rectangular plate), 4 (a small rectangular plate), 5 (a coiled power cord with a plug), 6 (a small rectangular plate), 7 (a small rectangular plate), 8 (a small rectangular plate), 9 (a small rectangular plate), 10 (a small rectangular plate), 11 (a small rectangular plate), 12 (a small rectangular plate), 13 (a small rectangular plate), 14 (a small rectangular plate), 15 (a small rectangular plate), 16 (a small rectangular plate), 17 (a small rectangular plate), 18 (a small rectangular plate), 19 (a small rectangular plate), 20 (a small rectangular plate), 21 (a small rectangular plate), 22 (a small rectangular plate), 23 (a small rectangular plate), 24 (a small rectangular plate), 25 (a small rectangular plate), 26 (a small rectangular plate), 27 (a small rectangular plate), 28 (a small rectangular plate), and 29 (a small rectangular plate). Dashed lines indicate the assembly path for each component.

Änderungen vorbehalten
Modifications reserved
Modifications reserves
Salvo modificaciones



Stand } ~~11-05-20~~
Issue } 11-10-26

Fig./Abb. 2

Änderungen vorbehalten
Modifications reserved
Modifications reserves
Salvo modificaciones

