



Fig./Abb. 1



WARNING! Electrical repairs should be attempted only by trained repairmen. Contact the nearest SKIL Service Center or other competent repair service.



WIRING DIAGRAM

Änderungen vorbehalten
 Modifications reserved
 Modifications reserves
 Salvo modificaciones