


F 016 310 542

Issue } 01-08-21
Stand }

Fig.1/Abb.1




Modifications reserved
Änderungen vorbehalten
Modifications reserves
Salvo modificaciones

F 016 310 542

Issue } 01-08-21
Stand }

Fig.2/Abb.2




Modifications reserved
Änderungen vorbehalten
Modifications reserves
Salvo modificaciones

F 016 310 542

Issue } 01-08-21
Stand }

Fig.3/Abb.3




Modifications reserved
Änderungen vorbehalten
Modifications reserves
Salvo modificaciones

F 016 310 542

Issue } 01-08-21
Stand }

Fig.4/Abb.4



Modifications reserved
Änderungen vorbehalten
Modifications reserves
Salvo modificaciones

[illegible]

This diagram illustrates the exploded view of a bicycle seat assembly. The components are labeled with part numbers: 75/20 (seat shell), 75/51 (top cap), 75/45 (top cap screw), 75/38 (top cap screw), 75/35 (top cap screw), 75/10 (cable), 75/09 (cable), 75/21 (cable), 875/04 (cable), 75/11 (cable), 75/37 (cable), 75/25 (cable), 75/37 (cable), 875/06 (cable), 75/10 (cable), 75/29 (cable), 75/01 (cable), 75/28 (cable), 875/03 (cable), and 75/10 (cable).

bb.6

65/01

65/08

65/09

65/04

865/06

65/05

65/07

65/12

65/02

65/21

65/22

65/23

65/24


65/26

65/25

65/20

65/03

Modifications reserved
Anderungen vorbehalten
Modifications reserves
Salvo modificaciones

Fig.7/Abb.7**Fig.8/Abb.8**